

MARYLAND HISTORICAL TRUST

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC 1525 Myrtle Avenue

MIHP No. B-5198

AND/OR COMMON

2 LOCATION

STREET & NUMBER

1500 Block Myrtle Avenue

CITY, TOWN

CONGRESSIONAL DISTRICT

— VICINITY OF

STATE

COUNTY

3 CLASSIFICATION

CATEGORY

☐ DISTRICT
☐ BUILDING(S)
☐ STRUCTURE
☐ SITE
☐ OBJECT

OWNERSHIP

☐ PUBLIC
☐ PRIVATE
☐ BOTH
PUBLIC ACQUISITION
☐ IN PROCESS
☐ BEING CONSIDERED

STATUS

☐ OCCUPIED
☐ UNOCCUPIED
☐ WORK IN PROGRESS
ACCESSIBLE
☐ YES: RESTRICTED
☐ YES: UNRESTRICTED
☐ NO

PRESENT USE

☐ AGRICULTURE ☐ MUSEUM
☐ COMMERCIAL ☐ PARK
☐ EDUCATIONAL ☐ PRIVATE RESIDENCE
☐ ENTERTAINMENT ☐ RELIGIOUS
☐ GOVERNMENT ☐ SCIENTIFIC
☐ INDUSTRIAL ☐ TRANSPORTATION
☐ MILITARY ☐ OTHER

4 OWNER OF PROPERTY

NAME

Telephone #:

STREET & NUMBER

CITY, TOWN

— VICINITY OF

STATE, zip code

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Liber #:

Folio #:

STREET & NUMBER Records Office Room 601

CITY, TOWN Baltimore City Courthouse

STATE

Baltimore, Maryland 21202

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

City of Baltimore Neighborhood Survey

DATE

1978

☐ FEDERAL ☐ STATE ☐ COUNTY ☐ LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

Commission for Historic and Architectural Preservation
STATE

Baltimore, Maryland 21202

7 DESCRIPTION

MIHP No. B-5198

CONDITION

☐ EXCELLENT
☐ GOOD
☐ FAIR

☐ DETERIORATED
☐ RUINS
☐ UNEXPOSED

CHECK ONE

☐ UNALTERED
☐ ALTERED

CHECK ONE

☐ ORIGINAL SITE
☐ MOVED DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The rowhouse is two bays wide and three stories high with a flat roof and proportional and symmetrical fenestration. The foundation and building walls are laid in running bond. The facade carries a brick water table. The foundation wall is punctuated by a flat boarded aperture with wood sill and painted stone lintel. The steps leading to the entrance that punctuates the right bay of the first story facade have been removed. That entrance is surmounted by a flat transom and a half arched brick lintel. The left bay of this facade is punctuated by double apertures for windows, that share a common mullion, painted wood sill, and half arched lintel. Either bay of the second and third story facades is punctuated by a flat aperture for a window with accompanying painted wood sills and raised painted wood surrounds. A painted wood cornice with brackets, dentals, and extra molding surmounts the building facade.

PERIOD		AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION	
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE	
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE	
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN	
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER	
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION	
<input type="checkbox"/> 1900	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)	
		<input type="checkbox"/> INVENTION			

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE


The 1500 block of Myrtle Avenue included houses of a variety of styles and sizes. Some were very ornately decorated, for example the window hoods of #1533. Others were simple and typical of housing in the area (#1531). The differing treatments of cornices, door and window lintels, and window sills provided a diversity along the streetscape. This block was razed c.1976.

CONTINUE ON SEPARATE SHEET IF NECESSARY

B-5198



1525 Myrtle Avenue
Sanborn Map 1953, Volume 2, Sheet 186

Demolished 1976



B-5198
1525 Myrtle Avenue
Block 0359 Lot 040
Baltimore City
Baltimore West Quad

Demolished





B-5198